

SALSA ON ICE REPORT: 27 October 2017

Weather

Weather conditions, light snow, winds gusting to 24 to 40 knots, temperature, minus 10C

SALSA Drillers on ice: Dar Gibson, Graham Roberts, Dennis Duling, Joshua Mehlin,

Drill Team Update:

- All flights cancelled due to weather delay.
- Started removing and replacing unistrut on side of Hose reel container for reattaching electrical components.
- Identified electrical circuit that need to be reconnected to electrical components.
- Drill team completed Field Safety course.

Cargo

- No cargo received.

Report by Dennis Duling